

HARDIN MARINE 11 Industry Dr. Palm Coast, FL 32137  
386-445-2500 / FAX 386-445-1122


PART NO.

FOR GEN 4 SEA PUMPS:  
625-4100  
625-4103  
625-4105  
625-4106  
625-4107  
625-4109  
625-4110  
625-4118  
625-4178


REPLACEMENT REBUILD KITS  
GEN 1:  
625-4173 MASTER REBUILD KIT  
625-4179 IMPELLER KIT  
  
GEN 2:  
625-4174 MASTER REBUILD KIT  
625-4189 IMPELLER KIT

TITLE:  
HARDIN GEN 4 SEA PUMP VERSIONS

www.hardin-marine.com



PIPE PLUG NOT USED IN GEN 2



GEN 1

GEN 2

FOR ALL HARDIN MERCURY GENERATION 4 REPLACEMENT SEA PUMPS YOU CAN IDENTIFY WHETHER YOU HAVE THE FIRST OR SECOND VERSION OF THESE PUMPS BY SIMPLY IDENTIFYING WHETHER YOUR PUMP HAS A 1/8" NPT BRASS DRAIN PLUG LOCATED ON THE UNDERSIDE OF THE PUMP HOUSING BETWEEN THE INLET/OUTLETS OF THE HOUSING, SEE FIG A. IF THE HOUSING IS OFF THE PUMP GEN 1 HAD A SLOT IN THE BODY, SEE FIG B.

NO TAB USED IN GEN 2